


Evaluation Roller / Compactor		www.mevas.eu	
Customer:	<i>Mercier</i>	vers 05-19	
Date:	<i>04/10/2019</i>		
Machine / type:	<i>HAMM HD 14 W</i>	Location:	<i>Vendeville France</i>
Serial No.:	<i>H2010726</i>	Hour reading:	<i>937</i>
Inspector:	<i>J.B.</i>	Year:	<i>2012</i>
CE <input type="checkbox"/> EPA <input type="checkbox"/>	A/C <input type="checkbox"/>	side cutter: <input type="checkbox"/>	side shift seat <input type="checkbox"/>
water spray <input checked="" type="checkbox"/>	compaction monitoring <input type="checkbox"/>	Parts book <input type="checkbox"/>	Op-Manual <input type="checkbox"/>
cab		cab doors	<i>n/a</i>
seat, arm rests	<i>good</i>	windows, mirrors	<i>n/a</i>
switches, controls	<i>good</i>	wipers, washer	<i>n/a</i>
gauges, warn lights	<i>good</i>	floor mat	<i>n/a</i>
aircon / heater	<i>n/a</i>	cab structure	<i>safety structure good</i>
engine	<i>KUBOTA V2203-M-EV33</i>	Serial No.	<i>7G-C9500</i>
leaks & seals	<i>no leaks</i>	cooling system	<i>good</i>
oil condition & level	<i>good</i>	blow by	<i>no visible vapor</i>
exhaust, muffler	<i>good</i>	belts & filters	<i>good</i>
smoke	<i>normal</i>	coolant condition	<i>good</i>
exterior		sheet metal, roof	<i>good</i>
chassis, frame	<i>good</i>	bumpers	
engine hood	<i>good</i>	lights	<i>headlights not operational</i>
steps, hand rails	<i>good</i>	paintwork	<i>good</i>
visual inspection	<i>check for cracks, re-welds, damages</i>		
axles, drive shafts	<i>n/a</i>	isolators	<i>good</i>
vibration motors	<i>good</i>	cleaner bars	<i>good</i>
hydraulics		oil level/condition	<i>good</i>
hoses & lines	<i>good</i>	pump and valve bloc	<i>good</i>
steering cylinders	<i>good</i>	pump noises	<i>normal</i>
functional test		vibration	<i>operational at all speeds</i>
steering	<i>good</i>	amplitude control	<i>good</i>
transmission	<i>good</i>	sprayer pump	<i>working</i>
speed control	<i>good</i>	park brake	<i>good</i>
tires / drum	measurement in mm		remaining live estimation %
front drum thickness	<i>17 mm, 80%</i>	front RHS tire	
rear drum thickness	<i>17 mm, 80%</i>	front LHS tire	
drum width	<i>1380 mm</i>	rear LHS tire	
		rear RHS tire	
additional attachments & features:			
<i>No CE label seen on machine.</i>			
problems, details:			
<i>Head- and backlights not working. Reverse lights OK.</i>			
<i>Roller in good working order. No major problems detected.</i>			
transport dimensions L x W x H in meter	<i>2.95 x 1.38 x 1.80 m</i>		